

- 1) "A" and "B" reset Box #1.
- 2) "A" and "B" sweep the tunnel to Box #2. If the Mini-Loop is good, reset Box #2 and continue. Else, "A" holds while "B" checks the tunnel to reset Box #2A.
- 3) "A" holds while "B" resets Box #3, sweeps the tunnel to reset Box #4.
- 4) "A" holds while "B" sweeps the tunnels to reset Box #5 and Box #6.
- 5) "A" and "B" reset Box #7 and Control Access out.

Reviewed AD/RSO

Date

Michael A. Gerardi

4-1-09

Approved AD/OPS Dept. Head

Date

[Signature]

4-2-09

CONTROLLED DOCUMENT


Users are responsible for ensuring they work to the latest approved revision. Printed or electronically transmitted copies are uncontrolled.

AD Enclosure - MI-4 P1 Line

Search and Secure Procedure

MI-4 P1 Line

MI4.V1.0



1. "A" holds, watches the P1 spur and door 528.
2. "B" enters at the 528 door, resets interlock box #5.
3. "B" looks for personnel in doorway 528 while enroute to interlock box #6.
4. "B" checks the P1 spur and resets interlock box #6.
5. "A" and "B" continues to interlock box #7.

Reviewed AD/RSO	Date
<i>Michael A. Gerard</i>	4-1-09
Approved AD/OPS Dept. Head	Date
<i>[Signature]</i>	4-2-09

CONTROLLED DOCUMENT

Users are responsible for ensuring they work to the latest approved revision. Printed or electronically transmitted copies are uncontrolled.

spb 17 Dec 2007
Version 1.0